

STIHL - 11230071004 - Juego engranaje y tornillo tensor de cadena motosierra STIHL

019T, 025, E160, HT102, HT103, HT131, HT133, HT56C, HT75, HTA65, HTA66, HTA85, HTE60, MS171, MS180 [2-MIX], MS181, MS190T, MS210, MS211, MS230, MS231, MS241C, MS251, MSA160T, MSE160C, MSE170C, MSE190C

Recambio original para las siguientes máquinas STIHL:

019T | 025 | E160 | HT102 | HT103 | HT131 | HT133 | HT56C-E | HT75 | HTA65 | HTA66 | HTA66-K | HTA85 | HTE60 | HT-KM | MS171 | MS180 [Versiones 2-MIX] | MS181 | MS190T | MS210 | MS211 | MS230 | MS231 | MS241C-M | MS251 | MSA160T | MSE160C-Q | MSE170C-Q | MSE190C-Q

Tipo de máquina: Motosierra, Podadora de altura

Referencias OEM STIHL: 11230071004, 1123 007 1004, 1123-007-1004

Denominaciones STIHL: Juego de tensado, Dispositivo de tensado, Juego engranaje recto / tornillo tensor

Modelo de STIHL: 019 T, 025, E 160, HT 102, HT 103, HT 131, HT 133, HT 56 C-E, HT 75, HTA 65, HTA 66, HTA 66-K, HTA 85, HTE 60, HT-KM, MS 171, MS 180 [Versiones 2-MIX], MS 181, MS 190 T, MS 210, MS 211, MS 230, MS 231, MS 241 C-M, MS 251, MSA 160 T, MSE 160 C-Q, MSE 170 C-Q, MSE 190 C-Q

Tipo de recambio: Original OEM

Fabricante: STIHL







