

## **STIHL - 11284051000 - Pipeta de bujía máquina STIHL**

Para STIHL MS170, MS171, MS180, MS192T, MS201, MS210, MS230, MS240, MS250, MS260, MS270, MS280, MS290, MS310

También para modelos MS341, MS360, MS361, MS362C, MS380, MS390, MS440, MS441, MS441C, MS460, MS461, MS640, MS650, MS660, MS661C, MS880, MS881, 009, 010, 011, 012, 017, 018, 020T, 021, 023, 024, 025, 026, 029, 039, 034, 036, 038, 044, 046, 056, 064, 066, 084, 088, FS160, FS180, FS235, FS490C, FS491C, FS510C, FS511C, FS560C, FS561C, FR235, TS400, TS410, TS420, TS440, TS460, TS500i, TS700, TS800, GS461

Referencias STIHL: 11284051000, 1128 405 1000, 1128-405-1000

Referencias equivalentes: 11134051000, 1113 405 1000, 1113-405-1000



